

```
1 ; history.txt - the version history file
2 ; [+] - add
3 ; [!] - changes
4 ; [v] - version
5 ; [+db] - additions to the database (DB)
6 ; [!db] - changes in the database
7 ; [-bd] - database optimization
8
9 24.03.2026
10 [v] 6.13.67.967
11 [+db] Address filtering improve
12
13 20.10.2025
14 [v] 6.13.67.964
15 [+db] There was added the system TPMS for Pajero Sport/Montero Sport (KR#,KS#)
16 [2016-2025]
17
18 13.10.2025
19 [v] 6.13.66.963
20 [+] Added model/system release years
21 [!] Revision/refactoring of the VIN processing code after adding the release codes
22 [+db]:
23 - Added systems to Eclipse Cross (GK#) [2018-2025]
24 - Added the Eclipse Cross (GL#) model [2021-2025] (not fully completed)
25 - Added the Pajero Sport/Montero Sport model (KR#,KS#) [2016-2025]
26 - Added systems to L200 (KA#,KB#) [2007-2015]
27 - Added EPB system to Outlander (GF#) [2013-2021]
28 - Added DTC polling in Steering Angle Sensor (SAS) system. (There were no errors in
29 the old version of MUTa)
30
31 03/09/2025
32 [in] 6.12.65.954
33 [!] Fix for Lifan Solano (620) in Delphi MT20U2-MT22U block
34 [!] Updated firmware files for MMC-Wireless adapter:
35 HW-2 v56-750.bin
36 HW-3 v11-750.bin
37 HW-4 v05-750.bin
38 [!] Code refactoring
39
40 08.10.2023
41 [v]6.12.65.933
42 [!] Bug fixed - added a table with error codes for Isuzu
43 [+db] Added models for VAZ
44 [!] The schema with an external directory for DTC tables has been returned. Tables
45 will be extracted to this folder as needed. This will also allow you to create
46 personalized tables with error codes, which was in the functionality of the
47 ELM-Reader scanner.
48
49 09/17/2023
50 [v] 6.12.64.929
51 [+] Checking the adapter firmware version has been returned
52
53 08/16/2023
54 [+] Added brands:
55 Ford trucks:
56 -
57
58 Foton trucks:
59 -Diesel 2.5L Delphi Common Rail;
60
61 Hyundai trucks:
62 -H1(SR) 2001-2008
63 -H1(SR) 2009-2011
64 -H100(HR) 2003-2007
65 -H100(HR) 2008-2012
66 -H100(HR) 2013-2016
67
68 Isuzu trucks:
69 -Amigo
70 -Axiom
71 -D-Max
```

```
67 -Frontier
68 -LUV, Rodeo, Frontier
69 -MU
70 -Rodeo
71 -TF/UC Series
72 -Trooper
73
74 Jeep:
75 -Grand Cherokee [1999-2004]
76 Grand Cherokee[2005-2010]
77
78 Lada:
79 -Granta
80 -Kalina
81 -Kalina_2
82 -Largus_2
83 -Niva[2005-2014]
84 -Priora
85 -Vesta
86 -XRay
87
88 Renault:
89
90 Nissan trucks:
91 Atlas - Cabstar F24 [2007-2013]
92 Atleon [2004-2005]
93 Atleon [2006-2008]
94
95 Mitsubishi fuso:
96 Fuso [2006-2011]
97 Fuso [2011-2013]
98 Fuso [2013-2018]
99
100 07/12/2023
101 [v] 6.12.63.924
102 [+db] FUSO cargo lines added (Mitsubishi\Europe\Fuso..2006-2018)
103 [!] The ru-RU.ini language file has been updated
104 [!] Technical improvements
105
106 05/11/2023
107 [v] 6.12.63.911
108 [!] Russian language for the first launch is set by default
109 [!] Changed the algorithm for reading error codes on the example of Toyota in case of
receiving multiline responses following a certain interval.
110
111 02/03/2023
112 [v] 6.12.62.907
113 [!] Fixed an error in detecting the MMC-Wireless adapter on the 4.1 platform
114
115 01/07/2023
116 [v] 6.12.61.880
117 [-] Built-in midas.dll library
118 [!db] Database updated, new error codes added
119 [!] Updated firmware versions: HW-2 v55.bin; HW-3 v05.bin
120 [+] Added legend for error code types: Stored, Pending
121 [+] Added a column with the error type on the DTC tab: Stored, Pending
122
123 01/05/2023
124 [+db] Updated database
125 [-] Removed the function of sending logs to cloud storage
126 [!] Only support for MMC-Wireless adapters is left
```